## HABS CAL 19-LOM,

## Historic American BuildingSSurvey

## Index to Photographs

HABS No. CA-2695

Harbor Hills Housing Project 26607 Western Avenue Lomita Los Angeles County California

Michael Moore, Photographer (September, 1998)

CA-2695-1	View from Western Avenue looking northwest down curbside walkway. Building 15 in left foreground. Illustration of asymmetrical layout and forty-five degree angle of buildings to public street.
CA-2695-2	Entryway view of interior pedestrian circulation and green space, with Building 7 on right foreground and Building 8 in left foreground. View facing southwest.
CA-2695-3	Detail of curved interior sidewalk and open space with Building 6 in background. View facing southwest.
CA-2695-4	Detail of multipaned steel casement windows at second floor level, also illustrating overhanging eave treatment. Building 4, facing northwest.
CA-2695-5	Detail of adjacent buildings illustrating spatial relationships and window placement. Buildings 16 and 17 facing south.
CA-2695-6	Detail illustrating multipaned steel casement windows breaking building corner. Building 27, facing northwest.
CA-2695-7	Window type: paired 3x2 multipaned steel window flanked by 1x3 multipaned steel casements, breaking building corner. Broad overhanging eave also illustrated. Second story detail. Building 13, facing east.
CA-2695-8	Window type: paired 2x4 multipaned steel windows flanked by 1x4 multipaned steel casements, breaking building corner. Raised panel door front entry also illustrated. Ground floor detail Building 19, facing north.
CA-2695-9	Window type: 2x3 fixed multipaned steel window flanked by 1x3 multipaned steel casements. Concrete sill and spandrel also illustrated. Building 43, facing east.
CA-2695-10	Window type: 4x4 multipaned steel window flanked by 1x4 multipaned steel casements. Concrete stoop, entry overhang and pipe rail detail also illustrated. Building 36, facing northwest.
CA-2695-11	Window types: (from left to right) Pair of 2x2 multipaned steel casements; triplet of 1x4 multipaned steel casements (center panel fixed); 1x3 multipaned steel casements. Building 20, facing southwest.
CA-2695-12	Internal pedestrian circulation and common open space, also illustrating mature landscape features. Building 35 at left foreground. Facing east.
CA-2695-13	Walkway and stairs. Building 26 at upper left. Facing southwest.

CA-2695-14 One of six dead-end "motor courts." Building 16 in the right mid ground. Facing west.

CA-2695-15 Brick incinerator structure located adjacent to "motor courts." This example is located between Buildings 26 and 27. Facing northeast.